

## AGENT VISUAL INSPECTION DISCLOSURE (CALIFORNIA CIVIL CODE § 2079 ET SEQ.)

For use by an agent when a transfer disclosure statement is OF REALTORS® required or when a seller is exempt from completing a TDS (C.A.R. Form AVID, Revised 11/13)

(C.A.R. For	m AVID, Revised 11/13	3)	
This inspection disclosure concerns the residential property single Riverside , State of California, de	tuated in the City of	Moreno Valley 23861 Betts Pl	, County of
Moreno Valley	CA 92553		("Property").
This Property is a duplex, triplex, or fourplex. This AVID formits	m is for unit #		required for other
nspection Performed By (Real Estate Broker Firm Name)		rusted Realty Advisors	
California law requires, with limited exceptions, that a real of competent and diligent visual inspection of reasonably and redisclose to the prospective purchaser material facts affecting duty applies regardless of whom that Agent represents. The units, and manufactured homes (mobilehomes). The duty also subdivision or a planned development) or to an attached dwo option to purchase, a ground lease or a real property sales core	normally accessible are the value or desirability duty applies to resident oplies to a stand-alone elling such as a condo ntract of one of those pr	as of certain properties offered y of that property that the inspe- tial real properties containing of detached dwelling (whether of minium. The duty also applies of minium.	ection reveals. The ne-to-four dwelling or not located in a
California law does not require the Agent to inspect the folloon.  Areas that are not reasonably and normally accessible.  Areas off site of the property.  Public records or permits.  Common areas of planned developments, condominiums, sites.		the like.	
Agent Inspection Limitations: Because the Agent's duty is lift reasonably and normally accessible areas of only the Prop do. What follows is a non-exclusive list of examples of limitation	mited to conducting a retry being offered for sa	easonably competent and dilige ale, there are several things that	nt visual inspection t the Agent will not
Roof and Attic: Agent will not climb onto a roof or into an	attic.		
Interior: Agent will not move or look under or behind fu chimneys or into cabinets, or open locked doors.			
Exterior: Agent will not inspect beneath a house or other plants, bushes, shrubbery and other vegetation or fences,	walls or other parriers.		
Appliances and Systems: Agent will not operate appliances heating cooling septic, sprinkler, communication, en	nces or systems (such tertainment, well or wat	er) to determine their functional	Ly.
Size of Property or Improvements: Agent will not measure lines, easements or encroachments.	sure square footage of	lot or improvements, or identify	or locate boundary
Environmental Hazards: Agent will not determine if the F	gic condition.		
Off-Property Conditions: By statute, Agent is not obligat or zoning, identify proposed construction or development	ed to null permits or ins	spect public records. Agent will i to transportation, schools, or la	not guarantee views w enforcement.
Analysis of Agent Disclosures: For any items disclosed an analysis of or determine the cause or source of the dis	as a result of Agent's v closed matter, nor dete	risual inspection, or by others, A rmine the cost of any possible re	gent will not provide epair.
What this means to you: An Agent's inspection is not intend a full and complete disclosure by a seller. Regardless of wh. California Law specifies that a buyer has a duty to exercise which are known to or within the diligent attention and observor not the Property meets their needs and intended uses, a SHOULD: (1) REVIEW ANY DISCLOSURES OBTAINED FITHE PROPERTY FROM OTHER APPROPRIATE PROPESSIONALS WITH THE PERSONS WHO PREPARED ADVICE OF BROKER.	ed to take the place of at the Agent's inspection reasonable care to protreation of the buyer. The s well as the cost to re- ROM SELLER; (2) OF	any other type of inspection, nor neveals, or what disclosures a sect himself or herself. This duty refore, in order to determine for emedy any disclosed or discoven a section of the content of the con	is it a substitute for are made by sellers, encompasses facts themselves whether ered defect, BUYER INSPECTIONS OF, NGS OF THOSE
Buyer's Initials () ()		Seller's Initials (	_)() /
The copyright laws of the United States (Title 17 U.S. Code) forbid the unauth reproduction of this form, or any portion thereof, by photocopy machine or any means, including facsimile or computerized formats. Copyright © 2007-2013, CALIFORNIA ASSOCIATION OF REALTORS®, INC. ALL RIGHTS RESERV AVID REVISED 11/13 (PAGE 1 OF 3)	other	byDate	FOULT HOUSING DEPORTUNITY

AGENT VISUAL INSPECTION DISCLOSURE (AVID PAGE 1 OF 3)

23861 Betts PI

erty Address: M	Moreno Valley, CA 92553	Date: <u>December 17 2018</u>			
is Property is a	a duplex, triplex, or fourplex, this AVID is for unit #				
	med By (Real Estate Broker Firm Name)				
	Time: <u>12/17/2018                                    </u>				
UNDERSIGN	esent: <i>Mell Hargo</i> NED, BASED ON A REASONABLY COMPETENT AND	DILIGENT VISUAL INSPECTION OF THE REASONABLY			
	Y ACCESSIBLE AREAS OF THE PROPERTY, STATES				
	common areas): See living room. Entry door has peeling	g paint. Screen entry door in poor condition with			
	broken handle.				
ing Room:	Wall patching behind entry door. Possible small stair	all stain at ceiling near southeast corner.			
ing Room:	Nothing appearing significant was visible. Some staining on kitchen counters. Screen door at patio sliding door in fair condition. The latch does not lock.				
chen:	Some staining on kitchen counters. Appliances appear to be older and not well maintained. Stain on floor in front of dishwasher. Ceiling light fixture peers to be damaged and may be missing part. Staining on ceiling North wall. Possible corrosion on water supply line in sink cabinet.				
ner Room:	N/A				
II/Stairs (aval	uding common areas): Nothing appearing to be signific	ant was visible.			
		ne and seal at bottom left corner of window frame.			
droom # <u>1</u>	: Southeast bedroom. Damage to interior window fran Appears to be staining on carpet near wall below win by strips of wood.				
droom # <u>1</u>	: Southeast bedroom. Damage to interior window fran Appears to be staining on carpet near wall below win	ne and seal at bottom left corner of window frame.			
droom # <u>1</u>	: Southeast bedroom. Damage to interior window fran Appears to be staining on carpet near wall below win by strips of wood.	ne and seal at bottom left corner of window frame.			
droom # <u>1</u>	: Southeast bedroom. Damage to interior window fran Appears to be staining on carpet near wall below window strips of wood.  : Master bedroom: 1) Nothing noted.	ne and seal at bottom left corner of window frame.			
edroom # _1_	: Southeast bedroom. Damage to interior window fran Appears to be staining on carpet near wall below window strips of wood.  : Master bedroom: 1) Nothing noted.	ne and seal at bottom left corner of window frame.			
edroom # _1_	: Southeast bedroom. Damage to interior window fran Appears to be staining on carpet near wall below window strips of wood.  : Master bedroom: 1) Nothing noted.  : N/A	ne and seal at bottom left corner of window frame.			
edroom # _ 1	: Southeast bedroom. Damage to interior window fran Appears to be staining on carpet near wall below window strips of wood.  : Master bedroom: 1) Nothing noted.  : N/A  Master bathroom. Fiberglass stall shower appears is sink faucet handle.  Hallway bathroom. Light fixture missing cover. Apple toilet on left hand side. Standing inside medicine care	ne and seal at bottom left corner of window frame. Indow. Exterior has visible gaps in window frame covered			
edroom # _1 : edroom # : ath#1 : ath#2 :	Southeast bedroom. Damage to interior window fram Appears to be staining on carpet near wall below window strips of wood.  Master bedroom: 1) Nothing noted.  N/A  Master bathroom. Fiberglass stall shower appears is sink faucet handle.  Hallway bathroom. Light fixture missing cover. App toilet on left hand side. Standing inside medicine cacabinet.	ne and seal at bottom left corner of window frame. Indow. Exterior has visible gaps in window frame covered  to have some staining. (2) crack at base of cold water  ears to have staining and possible wall damage behind			
edroom # _1 edroom # _2 edroom # ath#1:	: Southeast bedroom. Damage to interior window fran Appears to be staining on carpet near wall below window strips of wood.  : Master bedroom: 1) Nothing noted.  : N/A  Master bathroom. Fiberglass stall shower appears is sink faucet handle.  Hallway bathroom. Light fixture missing cover. Apple toilet on left hand side. Standing inside medicine care	ne and seal at bottom left corner of window frame. Indow. Exterior has visible gaps in window frame covered  to have some staining. (2) crack at base of cold water  ears to have staining and possible wall damage behind			
edroom # _1 : edroom # : ath#1 : ath#2 :	Southeast bedroom. Damage to interior window fram Appears to be staining on carpet near wall below window strips of wood.  Master bedroom: 1) Nothing noted.  N/A  Master bathroom. Fiberglass stall shower appears is sink faucet handle.  Hallway bathroom. Light fixture missing cover. App toilet on left hand side. Standing inside medicine cacabinet.	ne and seal at bottom left corner of window frame. Indow. Exterior has visible gaps in window frame covered  to have some staining. (2) crack at base of cold water  ears to have staining and possible wall damage behind			
edroom # _1 : edroom # : ath# : ath# :	<ul> <li>: Southeast bedroom. Damage to interior window fram Appears to be staining on carpet near wall below window strips of wood.</li> <li>: Master bedroom: 1) Nothing noted.</li> <li>: N/A</li> <li>Master bathroom. Fiberglass stall shower appears is sink faucet handle.</li> <li>: Hallway bathroom. Light fixture missing cover. Apptoilet on left hand side. Standing inside medicine cacabinet.</li> <li>: N/A</li> </ul>	ne and seal at bottom left corner of window frame. Indow. Exterior has visible gaps in window frame covered  to have some staining. (2) crack at base of cold water  ears to have staining and possible wall damage behind			
edroom # _1 : edroom # : edroom # : ath# : ath# : ther Room:	<ul> <li>: Southeast bedroom. Damage to interior window fram Appears to be staining on carpet near wall below window strips of wood.</li> <li>: Master bedroom: 1) Nothing noted.</li> <li>: N/A</li> <li>Master bathroom. Fiberglass stall shower appears is sink faucet handle.</li> <li>: Hallway bathroom. Light fixture missing cover. Apptoilet on left hand side. Standing inside medicine cacabinet.</li> <li>: N/A</li> </ul> None.	ne and seal at bottom left corner of window frame. Indow. Exterior has visible gaps in window frame covered  to have some staining. (2) crack at base of cold water  ears to have staining and possible wall damage behind abinet. Wall damage and hole on south wall inside sink			
edroom # _1	: Southeast bedroom. Damage to interior window fram Appears to be staining on carpet near wall below window by strips of wood.  : Master bedroom: 1) Nothing noted.  : N/A  Master bathroom. Fiberglass stall shower appears is sink faucet handle.  : Hallway bathroom. Light fixture missing cover. Appetoilet on left hand side. Standing inside medicine cacabinet.  : N/A  None.	ne and seal at bottom left corner of window frame. Indow. Exterior has visible gaps in window frame covered  to have some staining. (2) crack at base of cold water  ears to have staining and possible wall damage behind			

	3861 Betts Pl foreno Valley, CA 92553	Date: <u>Decer</u>	nber 17 2018			
If this Property is Other Room:	a duplex, triplex, or fourplex, this AVID is for unit #					
Other:	Garage Parking: Hanging drywall tape on ceiling near West Wall. Drywall tape missing in other locations on garage ceiling. Garage door bottom panel is bent.					
Other:	Patio and deck. Central air conditioning unit line to house appears insulation. Rain gutter outside patio appears to be in very poor	ioning unit line to house appears to be missing large amounts of io appears to be in very poor condition.				
Other:	Rear and side and front wood fencing, all appear to be in fair condition and have several areas that have been patched. Exterior wood trim flaking paint in many areas. Exterior stucco has staining in many locations. Rain gutter on east side in poor condition.					
Garage/Parking	excluding common areas): Driveway has cracks. Staining on garage floor. Inside garage west and south					
	walls not visible due to storage. Gap around water heater vent pipe at ceiling.					
Exterior Building	g and Yard -Front/Sides/Back: <u>Garage roll up door top rail is also</u> East Side chain link fence in fair condition. Wood fence all arou	o bent and makes sig und yard is in poor co	nificant noise. Front and			
	or Known Conditions Not Specified Above: Roof appears to has shingles. Roof shingles are discolored throughout. Unable to o	pen electric breaker	circuit panel box.			
areas of the Pro	is based on a reasonably competent and diligent visual insponenty on the date specified above.  er/(Firm who performed the Inspection)	ection of reasonably STED REALTY ADVIC				
By A	( Atmon)	Date <u>12</u> /				
Reminder: Not testing of any s ADVICE ABOUT DO SO, BUYER	(Signature of Associate Licensee or Broker)  ELL AND OR MELL HARGO  all defects are observable by a real estate licensee conducting system or component. Real Estate Licensees are not home inspersional NISPECTIONS OF THE PROPERTY FROM OTHER APPROIS ACTING AGAINST THE ADVICE OF BROKER.	PRIATE PROFESSIO	DO LEIVOUGGED OB IT III.			
I/we acknowled	ge that I/we have read, understand and received a copy of this d		Dete			
SELLER	Probate - Exe		Date Date			
SELLER	Probate - Exe	inpt	Date			
BUYER			Date			
BUYER	<u> </u>					
By ///.//	ker (Firm Representing Seller)	ed Realty Advisors	Date <u>12/17/2018</u>			
Real Estate Bro	ker (Firm Representing Buyer)		Date			
Ву	(Associate Licensee or Broker Signature)					
including facsimile of THIS FORM HAS B ADEQUACY OF A TRANSACTIONS. I	of the United States (Title 17 U.S. Code) forbid the unauthorized reproduction of this form, in computerized formats. Copyright ©2007, CALIFORNIA ASSOCIATION OF REALTORS (C.A.R.). NO EEN APPROVED BY THE CALIFORNIA ASSOCIATION OF REALTORS (C.A.R.). NO NY PROVISION IN ANY SPECIFIC TRANSACTION. A REAL ESTATE BROKER IF YOU DESIRE LEGAL OR TAX ADVICE, CONSULT AN APPROPRIATE PROFESSION IN SECURITY OF THE PROFESSION OF THE PROFES	REPRESENTATION IS MAI S THE PERSON QUALIFIE NAL. ALTOR®, REALTOR® is a r	DE AS TO THE LEGAL VALIDITY OF ED TO ADVISE ON REAL ESTAT			

Published and Distributed by:
REAL ESTATE BUSINESS SERVICES, INC.
a subsidiary of the CALIFORNIA ASSOCIATION OF REALTORS® 525 South Virgil Avenue, Los Angeles, California 90020

Date Reviewed by

