



Berry Roofing, Inc., Lic.#691947
Serving Inland Empire & Orange County for over 25
years! www.berryroofing.com
Phone: (800) 590-5838
Fax: (951) 905-5117

Company Representative
Jean de Jong
Phone: (951) 255-8879
jean@berryroofing.com

ESTIMATE

07/26/2017
Claim Information

Jasmine Mavi
19917 Silvercrest Lane, Riverside, CA 92508
(951) 201-1009

Job: 19941: Jasmine Mavi

Tile repair - Leak behind front Door

	Qty	Unit
1 man	4.00	EA
Supply and install 2 layers of American Made 30lb Fontana Felt Paper	1.50	SQ
3/4" Plastic Cap Nails	0.20	EA
Bull Noses/mudd balls at all intersections of hip and ridges	1.00	EA
Gas Surcharge - NO CHARGE	50.00	EA
For Repairs: Berry Roofing Inc shall hold a Limited 2 year workmanship warranty on repairs, although shall not be held responsible for property damages at any time.	1.00	EA

Repair Labor Cost

This is the total labor cost associated with the repairs needed

\$879.22

Tile repair - Leak below Chimney

	Qty	Unit
1 man	3.00	EA

Repair Labor Cost

This is the total labor cost associated with the repairs needed

\$579.54

Sub Total \$1,458.76

Tax \$23.29

TOTAL \$1,482.05

THANK YOU VERY MUCH FOR CONSIDERING US! ***** SAFETY, QUALITY, DEPENDABILITY ***** "WE STRIVE TO USE ALL AMERICAN MADE PRODUCTS ON YOUR ROOF!"

Safety is our number one concern. All work performed will be managed over and beyond the requirements of CAL OSHA. Please inform us of any special concerns that you may have at the beginning of the project. The safety precautions taken are enforced in order to protect the consumer and our workers and to make sure the re-roofing experience is as stress free as possible. All men are required to tie off ladders, wear hard hats, safety glasses, safety harness and cables for a safe work environment.



Company Representative
Jean de Jong
Phone: (951) 255-8879
jean@berryroofing.com

Larger
200 View

Jasmine Mavi
19917 Silvercrest Lane, Riverside, CA 92508

Job: 19941: Jasmine Mavi

~~19917201-1009~~

Tile repair - Leak behind front Door

	Qty	Unit
1 man	4.00	EA
Supply and install 2 layers of American Made 30lb Fontana Felt Paper	1.50	SQ
3/4" Plastic Cap Nails	0.20	EA
Bull Noses/mudd balls at all intersections of hip and ridges	1.00	EA
Gas Surcharge - NO CHARGE	50.00	EA
For Repairs: Berry Roofing Inc shall hold a Limited 2 year workmanship warranty on repairs, although shall not be held responsible for property damages at any time.	1.00	EA

Repair Labor Cost

This is the total labor cost associated with the repairs needed

\$879.22

Tile repair - Leak below Chimney

	Qty	Unit
1 man	3.00	EA

Repair Labor Cost

This is the total labor cost associated with the repairs needed

\$579.54

Sub Total	\$1,458.76
Tax	\$23.29
TOTAL	\$1,482.05

3226 Kluk Ln.
Riverside, CA 92501
www.berryroofing.com
Ph 951-905-5116

License # 691947

Invoice

P.O. #: J-19941

BILL TO:

Jasmine Mavi
19917 Silvercrest Lane
Riverside, CA 92508

**THE BERRY BEST IN
ROOFING**

Web Site

berryroofing.com

DATE: 8/8/2017

INVOICE # 19941_1

TERMS: Due Upon Receipt

JOBSITE ADDRESS:

19917 Silvercrest Lane
Riverside, CA 92508

DESCRIPTION	SERVICED	Prev. Invoiced	AMOUNT
Tile repair - Leak behind front Door Tile repair - Leak below Chimney			879.27 602.83
<div> <div>Payments/Credits</div> </div>	-51,482.05		
<div>Balance Due</div>			\$0.00

All return checks are subject to a \$35.00 Service Charge. A finance charge of 24% APR. In the event legal action to recover, all costs including attorneys fees will be paid by other party whether or not action is filed. All legal action will be conducted in the jurisdiction and under the laws of the State of California.

