



CALIFORNIA
ASSOCIATION
OF REALTORS®

**AGENT VISUAL INSPECTION DISCLOSURE
(CALIFORNIA CIVIL CODE § 2079 ET SEQ.)**
For use by an agent when a transfer disclosure statement is
required or when a seller is exempt from completing a TDS
(C.A.R. Form AVID, Revised 11/13)

This inspection disclosure concerns the residential property situated in the City of Yucca Valley, County of _____, State of California, described as 7407 Barberry Ave ("Property").

This Property is a duplex, triplex, or fourplex. This AVID form is for unit # _____. Additional AVID forms required for other units.

Inspection Performed By (Real Estate Broker Firm Name) Trusted Realty Advisors

California law requires, with limited exceptions, that a real estate broker or salesperson (collectively, "Agent") conduct a reasonably competent and diligent visual inspection of reasonably and normally accessible areas of certain properties offered for sale and then disclose to the prospective purchaser material facts affecting the value or desirability of that property that the inspection reveals. The duty applies regardless of whom that Agent represents. The duty applies to residential real properties containing one-to-four dwelling units, and manufactured homes (mobilehomes). The duty applies to a stand-alone detached dwelling (whether or not located in a subdivision or a planned development) or to an attached dwelling such as a condominium. The duty also applies to a lease with an option to purchase, a ground lease or a real property sales contract of one of those properties.

California law does not require the Agent to inspect the following:

- Areas that are not reasonably and normally accessible
- Areas off site of the property
- Public records or permits
- Common areas of planned developments, condominiums, stock cooperatives and the like.

Agent Inspection Limitations: Because the Agent's duty is limited to conducting a reasonably competent and diligent visual inspection of reasonably and normally accessible areas of only the Property being offered for sale, there are several things that the Agent will not do. What follows is a non-exclusive list of examples of limitations on the scope of the Agent's duty.

Roof and Attic: Agent will not climb onto a roof or into an attic.

Interior: Agent will not move or look under or behind furniture, pictures, wall hangings or floor coverings. Agent will not look up chimneys or into cabinets, or open locked doors.

Exterior: Agent will not inspect beneath a house or other structure on the Property, climb up or down a hillside, move or look behind plants, bushes, shrubbery and other vegetation or fences, walls or other barriers.

Appliances and Systems: Agent will not operate appliances or systems (such as, but not limited to, electrical, plumbing, pool or spa, heating, cooling, septic, sprinkler, communication, entertainment, well or water) to determine their functionality.

Size of Property or Improvements: Agent will not measure square footage of lot or improvements, or identify or locate boundary lines, easements or encroachments.

Environmental Hazards: Agent will not determine if the Property has mold, asbestos, lead or lead-based paint, radon, formaldehyde or any other hazardous substance or analyze soil or geologic condition.

Off-Property Conditions: By statute, Agent is not obligated to pull permits or inspect public records. Agent will not guarantee views or zoning, identify proposed construction or development or changes or proximity to transportation, schools, or law enforcement.

Analysis of Agent Disclosures: For any items disclosed as a result of Agent's visual inspection, or by others, Agent will not provide an analysis of or determine the cause or source of the disclosed matter, nor determine the cost of any possible repair.

What this means to you: An Agent's inspection is not intended to take the place of any other type of inspection, nor is it a substitute for a full and complete disclosure by a seller. Regardless of what the Agent's inspection reveals, or what disclosures are made by sellers, California Law specifies that a buyer has a duty to exercise reasonable care to protect himself or herself. This duty encompasses facts which are known to or within the diligent attention and observation of the buyer. Therefore, in order to determine for themselves whether or not the Property meets their needs and intended uses, as well as the cost to remedy any disclosed or discovered defect, **BUYER SHOULD: (1) REVIEW ANY DISCLOSURES OBTAINED FROM SELLER; (2) OBTAIN ADVICE ABOUT, AND INSPECTIONS OF, THE PROPERTY FROM OTHER APPROPRIATE PROFESSIONALS; AND (3) REVIEW ANY FINDINGS OF THOSE PROFESSIONALS WITH THE PERSONS WHO PREPARED THEM. IF BUYER FAILS TO DO SO, BUYER IS ACTING AGAINST THE ADVICE OF BROKER.**

Buyer's Initials (____) (____)

Seller's Initials (Exempt
Probate)

The copyright laws of the United States (Title 17 U.S. Code) forbid the unauthorized reproduction of this form, or any portion thereof, by photocopy machine or any other means, including facsimile or computerized formats. Copyright © 2007-2013, CALIFORNIA ASSOCIATION OF REALTORS®, INC. ALL RIGHTS RESERVED.

AVID REVISED 11/13 (PAGE 1 OF 3)

Reviewed by _____ Date _____



AGENT VISUAL INSPECTION DISCLOSURE (AVID PAGE 1 OF 3)

Trusted Realty Advisors, 7241 Palm Ave STE 200 Highland, CA 92346-3262
Jim Trammell

Phone: 909-962-0102

Fax:

Barberry 7407 -

Produced with zipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 www.zipLogix.com

7407 Barberry Ave

Property Address: Yucca Valley, CA 92284

Date: February 1 2017

If this Property is a duplex, triplex, or fourplex, this AVID is for unit # _____ .

Inspection Performed By (Real Estate Broker Firm Name) Trusted Realty Advisors

Inspection Date/Time: 02/01/2017 3:45PM Weather conditions: Clear and cloudy

Other persons present: Mell Hargo

THE UNDERSIGNED, BASED ON A REASONABLY COMPETENT AND DILIGENT VISUAL INSPECTION OF THE REASONABLY AND NORMALLY ACCESSIBLE AREAS OF THE PROPERTY, STATES THE FOLLOWING:

Entry (excluding common areas): See Living room

Living Room: Limited visibility due to personal property. Damage to vinyl flooring at entry door.

Dining Room: Limited visibility due to personal property. Stain and bubbling on ceiling between dining room and kitchen.

Kitchen: Limited visibility due to personal property and trash. Filthy. Floor covering is stained. Stained ceiling inside upper cabinet closest to dining room.

Other Room: N/A

Hall/Stairs (excluding common areas): Torn and missing vinyl flooring where hall meets rear bedroom.

Bedroom # 1 : (front) Limited visibility due to personal property. It appears that a former window has been framed in for a wall air conditioning unit. Door to room from hall is damaged.

Bedroom # 2 : (rear) Limited visibility due to personal property. Staining in closet where walls and ceiling meet. It appears that a former window has been framed in for a wall air conditioning unit.

Bedroom # _____ : N/A

Bath# 1 : (front bedroom) Plaster damage on wall between shower and toilet, also on wall behind toilet. Possible mold on wall below sink. Missing shower head. Wall damage above tile in shower stall.

Bath# 2 : (hall) Discoloration in tub. Unable to inspect under vanity due to personal property.

Bath# _____ : N/A

Other Room: N/A

Buyer's Initials (_____) (_____)

Seller's Initials (_____) (_____) *Exempt Probate*

Copyright © 2013, CALIFORNIA ASSOCIATION OF REALTORS®, INC.
AVID REVISED 11/13 (PAGE 2 OF 3)

Reviewed by _____ Date _____

AGENT VISUAL INSPECTION DISCLOSURE (AVID PAGE 2 OF 3)

Produced with zipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 www.zipLogix.com

Barberry 7407 -



Property Address: 7407 Barberry Ave
Yucca Valley, CA 92284

Date: February 1 2017

If this Property is a duplex, triplex, or fourplex, this AVID is for unit # _____ .

Other Room: N/A

Other: N/A

Other: N/A

Other: N/A

Garage/Parking (excluding common areas): Limited visibility due to personal property. Crack in concrete outside rear garage door.

Exterior Building and Yard -Front/Sides/Back: Facia boards, eaves, garage door and other wood trim have peeling paint and some staining. Front brick planter appears to have been damaged by tree. Framed in windows have unpainted exterior wood.

Other Observed or Known Conditions Not Specified Above: None.

This disclosure is based on a reasonably competent and diligent visual inspection of reasonably and normally accessible areas of the Property on the date specified above.

Real Estate Broker (Firm who performed the Inspection) Trusted Realty Advisors
By Jim Trammell Date 02/01/2017
(Signature of Associate Licensee or Broker)

Jim Trammell

Reminder: Not all defects are observable by a real estate licensee conducting an inspection. The inspection does not include testing of any system or component. Real Estate Licensees are not home inspectors or contractors. BUYER SHOULD OBTAIN ADVICE ABOUT AND INSPECTIONS OF THE PROPERTY FROM OTHER APPROPRIATE PROFESSIONALS. IF BUYER FAILS TO DO SO, BUYER IS ACTING AGAINST THE ADVICE OF BROKER.

I/we acknowledge that I/we have read, understand and received a copy of this disclosure.

SELLER _____ Date _____
SELLER _____ Date _____
BUYER _____ Date _____
BUYER _____ Date _____

Real Estate Broker (Firm Representing Seller) Trusted Realty Advisors
By Jim Trammell Date 02/01/2017
(Associate Licensee or Broker Signature)

Real Estate Broker (Firm Representing Buyer) _____
By _____ Date _____
(Associate Licensee or Broker Signature)

The copyright laws of the United States (Title 17 U.S. Code) forbid the unauthorized reproduction of this form, or any portion thereof, by photocopy machine or any other means, including facsimile or computerized formats. Copyright ©2007, CALIFORNIA ASSOCIATION OF REALTORS®, INC. ALL RIGHTS RESERVED. THIS FORM HAS BEEN APPROVED BY THE CALIFORNIA ASSOCIATION OF REALTORS® (C.A.R.). NO REPRESENTATION IS MADE AS TO THE LEGAL VALIDITY OR ADEQUACY OF ANY PROVISION IN ANY SPECIFIC TRANSACTION. A REAL ESTATE BROKER IS THE PERSON QUALIFIED TO ADVISE ON REAL ESTATE TRANSACTIONS. IF YOU DESIRE LEGAL OR TAX ADVICE, CONSULT AN APPROPRIATE PROFESSIONAL. This form is available for use by the entire real estate industry. It is not intended to identify the user as a REALTOR®. REALTOR® is a registered collective membership mark which may be used only by members of the NATIONAL ASSOCIATION OF REALTORS® who subscribe to its Code of Ethics.

Published and Distributed by:
REAL ESTATE BUSINESS SERVICES, INC.
a subsidiary of the CALIFORNIA ASSOCIATION OF REALTORS®
525 South Virgil Avenue, Los Angeles, California 90020

AVID REVISED 11/13 (PAGE 3 OF 3)

Reviewed by _____ Date _____



AGENT VISUAL INSPECTION DISCLOSURE (AVID PAGE 3 OF 3)

Produced with zipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 www.zipLogix.com

Barberry 7407 -